

TARGET STATION INFRASTRUCTURE

THE **CNGS** EXPERIENCE

Workshop on Applications of High Intensity Proton Accelerators

October 19-21, 2009

Fermi National Accelerator Laboratory
Batavia, IL, USA

*Exploring the challenges and opportunities
for building a high-intensity proton
accelerator with superconducting
radiofrequency technology*

- Discovery Science
- Accelerator Driven Nuclear Energy
- Material Science

For workshop information and registration:
<http://conferences.fnal.gov/App-Proton-Accelerator/index.html>



Fermilab

U.S. DEPARTMENT OF
ENERGY

Fermi
Research
Alliance LLC

Outline

- Introduction to CNGS
- Review on issues since the startup of the facility in 2006
- Lessons learned – things we would do differently today

D. Autiero, **I. Efthymiopoulos**, A. Ferrari, **E. Gschwendtner**, A. Guglielmi, A. Pardons, P. Sala, **H. Vincke**, J. Wenninger

Workshop on Applications of High Intensity Proton Accelerators
Dresden, October 23, 2008




CERN Neutrinos to Gran Sasso


2 Introduction

Principle

- At CERN: Produce a beam of ν_μ neutrinos at CERN pointing towards Gran Sasso using an intense proton beam extracted from SPS at 400 GeV/c impinging a graphite target
- At Gran Sasso: detect the ν_τ neutrinos resulting from the oscillation of ν_μ neutrinos in the ~ 730 km of earth
 - ν_τ appearance optimized experiments: OPERA (~ 1.2 kt), ICARUS (600 t)



Signal event




Background event







CERN Neutrinos to Gran Sasso

3 Facility layout



4 The secondary beam



Proton beam parameters



Energy	400 GeV/c
Cycle length	<ul style="list-style-type: none"> • 6 seconds • 2 extractions/cycle, 50ms apart
Extraction	<ul style="list-style-type: none"> • 2.4×10^{13} protons • 10.5 μs long pulse
Beam power	• 510 kW

- Installation completed in **June 2006**
- Commissioning in 2006
- In operation since **2007**
- 4.5×10^{19} protons/year** – 5 year program
 - $\sim 3.5 \times 10^{11} \nu_\mu$ / year at Grand Sasso
 - ~ 3000 CC ν_μ interactions/kt/year at the experiment
 - $\sim 2 \div 3 \nu_\tau$ interactions detected/year (OPERA)

Key elements of the secondary beam

5 The target station

- Interspaced **graphite rods**, to optimize pion production
 - ▣ 10cm long, 5(4) mm \varnothing , 200 cm ($\sim 2.7 \lambda_{\text{int}}$) total length





Key elements of the secondary beam

6

The magnetic horns

- Current: **150kA (horn) – 180 kA (reflector)**
 - ▣ Pulse duration 7ms



CNGS – horn:


- ~7m long, 700mm \varnothing
- Inner conductor:
1.8mm thick,
30÷136mm \varnothing
- Made of Aluminum
- Water cooled




Key elements of the secondary beam

7

Radiation environment



- Optimized shielding
 - ↪ Marble – iron – concrete
 - ↪ Remote handling



- Remote station for radiation survey in the target chamber





CNGS Target Area

8 Design baseline

- The target area design in a high-power v-beam is always very challenging :
 - ▣ the target must sustain the energy deposition and induced stress waves from the beam impact
 - ▣ the choice of materials has to be adopted to the high-radiation environment
 - ▣ the high remnant radiation environment limits access possibilities for service & maintenance
- **CNGS baseline :**
 - ▣ over-designed using safety factors for present and future intensity upgrades
 - ▣ provision for spares of the most sensitive equipment and well studied exchange procedures (HAZOP)

M.Meddahi, E.Schaposnicova - CERN-AB-2007-013 PAF

I per PS batch	# PS batches	I per SPS cycle	200 days, 100% efficiency, no sharing	200 days, 55% efficiency, no sharing	200 days, 55% efficiency, 60% CNGS sharing
		[prot./6s cycle]	[pot/year]	[pot/year]	[pot/year]
2.4×10 ¹³ - Nominal CNGS	2	4.8×10 ¹³	1.38×10 ²⁰	7.6×10 ¹⁹	4.56×10 ¹⁹
3.5×10 ¹³ - Ultimate CNGS	2	7.0×10 ¹³	(2.02×10 ²⁰)	(1.11×10 ²⁰)	(6.65×10 ¹⁹)

Design limit for the target (bracketed around 2.4×10¹³)

CNGS working hypothesis (bracketed around 7.6×10¹⁹)

working hypothesis for RP calculations (bracketed around 7.0×10¹³)

I.Efthymiopoulos, CERN



CNGS Operation

9

Summary

Year	Protons on target
2006-comm.	6.87×10^{15}
2006	8.48×10^{17}
2007-comm.	5.0×10^{16}
2007	7.86×10^{17}
2008	1.78×10^{19}
2009	2.55×10^{19} (today) 3.20×10^{19} (expected)

2006- run


- failure in reflector cooling circuit

2007- run

- radiation effects on ventilation system electronics
- broken flexible stripline cable

2008- shutdown

- failure in target rotation mechanism – inspection
- horn/reflector cooling system filter improvements
- handling of tritiated water



☞ further info on CNGS operation performance: talk by **E. Gschwendtner (WG1 - Tuesday PM)**




CNGS Operation

10

Summary

- Focusing on the problems we had, should be balanced with the smooth startup, commissioning and operation of the facility which will soon complete a second year of physics with the maximum available intensity from CERN/SPS.
- Important to notice the early failures we had or “teething problems”, were on peripheral components
 - ▣ **Lesson #1** : the design of the identified critical items typically receives most of the attention and is well done – or at least we know what to do in case of failures. The reality says the problem often comes from the peripheral components receiving less of attention or not subject to the same rigorous quality assurance
 - the LHC experience for the QRL installation and cable splicing problem confirms it as well
- Since the failures happened too early, we were forced to do unforeseen interventions for repairs – too early to waste our spares!
 - ▣ **Lesson #2** : tooling and procedures for interventions to repair early failures should be included in the design of a facility
- We profited from the repair work to do improvements and preventive maintenance on similar elements installed on other equipment


Horn & Reflector issues



- ❑ Observed high refill rate in the closed circuit water cooling system of the reflector, and increased water level in the sumps
- ↪ fault in one of the ceramic insulating connectors of the reflector

Horn & Reflector issues



Water outlets



❑ Old design

- Ti-ceramic assembly, **machined, brazed**
- Bellows absorbs misalignments
- Shear stress from brazing (thermal) too high
- Non optimal geometry for the ceramic

Water inlets



❑ New design

- **No brazing**, no machining, soft seal, **ceramic only in compression**
- Thorough testing in the spare horn
- Replaced all water inlets & outlets in horn & reflector

Horn & Reflector issues

13 Water inlets & Outlets repair & improvements



- ❑ Only possible since we haven't been running for long
- ❑ Work in a radioactive environment:
 - ↪ detailed radiation dose planning and minimization before intervention
 - ↪ **practice sessions with spare horn**
 - ↪ dose sharing
 - ↪ additional mobile local shielding





Horn & Reflector issues

14 Stripline repair & improvements

Old design for flexible part

- Clamped plates, twisted cables, **brazed**
- No control of the large magnetic forces during pulsing (measured $\pm 2\text{mm}$)
- The cable was finally broken due to fatigue after $\sim 300\text{k}$ pulses





- Stripline plates and cables during pulsing
- Images recorded at 1kHz, playback 40 times slower





Metallurgical analysis of the broken cable:

- Beach marks
- Striations
- Secondary cracks



A. Gerardin, G. Arnau Izquierdo, CERN – TS/MME


I.Efthymiopoulos, CERN



- Preventive maintenance : replace all flexible striplines of both horns

□ New design

- No brazing, semi-flexible (allows for thermal dilatation) fully clamped plates
- Vibrations during pulsing reduced to ± 0.2 mm
- No change in the impedance or current flow properties





- Resin filters are used to maintain a low conductivity level in the cooling circuit
 - ▣ Two reasons:
 - avoid short-circuit inside the horn
 - limit long-term corrosion effects
 - ▣ About 1/3 of the flow goes through the filters
 - ▣ Required level: **[0.1,10.0]μS/cm**

- Two filters in place (active + spare) equipped with quick connectors
 - ▣ Filters get activated – moved to temporarily storage for initial cool-down before taken to waste


Main issues:

- Filter lifetime - saturation
 - ▣ wished to be one year, but difficult to estimate
 - ▣ 2008 run showed they saturate much sooner !!
 - ▣ long access (>20h stop) each time to replace them (10min)
- We discovered the filters had plastic pieces (tubes) inside; not a real issue but better to avoid
- The filters are radioactive waste, their use must be optimized



Horn & Reflector issues

17 Cooling system filters lifetime



- ❑ Use of original filter cartridges would imply **~6** filter exchanges for a nominal CNGS year (4.5×10^{19} pot) !

New home-made cartridge design

- ❑ Increase $\times 2.5$ the filter capacity of the system \rightarrow one exchange / year
 - modify piping to accept more filters in parallel
- ❑ Optimized design
 - \rightarrow maintain the quick connectors and optimize manipulation (installation/removal) operations
 - \rightarrow easy emptying of the resin material allows re-use of the cartridges \rightarrow less waste





Horn & Reflector issues

19

Lessons learned

3. Careful and “safe” engineering with well known and calculable techniques should be preferred
 - ▣ brazing better to be avoided ; use ceramics in compression only
 - ▣ design modifications should be accompanied with studies and calculations – e.g. avoid last minute machining
 - ▣ sounds trivial but for screws/bolts : use same size for same purpose, think their position and manipulation in a future intervention
 - ▣ maintain a good record of installed elements with photos/videos

4. Forces in high-current conductors should be considered in the design
 - ▣ include dynamic studies not only static
 - ▣ risky to extrapolate from known configurations

5. In high-radiation environment interventions, planning, analysis and practice is essential to minimize the dose

6. For “consumables” , optimization of the radioactive waste should be included in the design
 - ▣ balance between commercial (easy to get) components and home-made designs


Radiation effects on electronics

20 Failure of ventilation system electronics


- ❑ All CNGS electronics were installed in the service gallery and upstream cavern
 - ↪ At that time only personnel dose and not SEE to electronics were considered
 - ↪ Radiation levels during operation exceed the limits COTS electronics can withstand → also triggered a LARGE campaign for LHC !!
- ❑ The ventilation system electronics in the service gallery failed first (only at 10^{16} pot!), all the rest would have followed if we had been running longer



● Ventilation units in the TSG4 gallery




High-energy (>20MeV) hadrons fluence (h/cm^2) for $4.5E19$ pots (1-year)



FLUKA Simulation : L.Sarchiapone et. al, 2008

Radiation effects on electronics

21 Protecting the electronics – additional shielding





- Group all the electronics in a single area
- Add shielding to reduce the radiation levels ; opted for $\times 1000$ reduction
 - ↳ Concrete walls up to 6m thick, **$\sim 53\text{m}^3$ of concrete** in total were installed!

“radiation safe” areas for electronics

Shielding in TSG41 tunnel
Towards the target chamber



High-energy (>20MeV) hadrons fluence (h/cm^2) for $4.5\text{E}19$ pot



FLUKA Simulation : L.Sarchiapone et. al, 2008



Radiation effects on electronics

22



Lessons learned

7. Radiation effects (single event effects) to commercial electronics (COTS) is a reality and must be taken seriously into account
 - ▣ installed electronics – typically from services (ventilation, power, access systems, cranes, etc.)
 - ▣ but also for equipment during interventions
8. Recommendation: no electronics in beam tunnels, target and proximity areas where streaming radiation (neutrons) can exceed normal “office” limits
 - ▣ customizing COTS components would increase substantially the cost and doesn't really solve the problem for installations with >10 years lifetime – new versions, upgrades, etc.
9. Availability of “as build” simulations is a mandatory tool to understand and evaluate the radiation environment in a facility
 - ▣ helps primarily for personnel protection, but also to schedule works during interventions

Target motorization failure

23 Target station design with in-situ spares


- Target assembly:
 - 5 target units (almost identical)
 - empty positions in between for beam tuning
 - rotation with DC motors and torque limiter outside the shielding.
- Increased torque observed in the rotation motor during annual maintenance on March'09
- From a first inspection outside the shielding signs of rust observed in parts of the motorizations and limit switches
 - ↪ Expected due to the radiation environment



Target motorization failure

24 In-situ inspection (April 8-9, 2008)

Target rotation mechanism – view from web cam



Target view through the Pb-glass window



Area preparation : additional shielding & protection



The operations were monitored remotely using the crane and additional web cameras

Target motorization failure

25 In-situ inspection (April 8-9, 2008)



Summary of observations:

- all four ball-bearings have signs of rust
- 3 turn when the barrel moves but with difficulty
- 1 doesn't turn at all in one direction (at least at startup)

- Discussing again with the supplier we discovered that contrary to the specifications the pieces delivered were treated with a lubricant (YVAC3) thought to be radiation hard

- New set without lubricant ordered and is under test in the target. Another alternative is the use of ceramic ball-bearings (higher cost)



Target motorization failure

26

Lessons learned

10. Rigorous quality assurance for all pieces is vital
 - a chain is as strong as its weakest link

11. Foresee tooling and procedures to observe the components that fail, before exchanging them with spares
 - understanding the origin of the failure may impact on the decision of using the available spares!




- Leak of chilled water circuit in one of the TCV4 units installed in the access cavern (**1st floor**)
 - ▣ small leak, triggered no alarm, but until it was detected **~2.5m³ of water** dripped on the floor and on equipment
 - ▣ fortunately only minor damages
 - ▣ the water became radioactive as it washed the nearby filters of the ventilation unit
 - ▣ ended up in the sump of the cavern contaminating the clean drain water in there that had to be pumped
- Repaired on time for the 2009 startup with beam

Lesson #12 : A clear separation between the systems that service the radiation areas from the rest should be made

- This may imply constructing **additional tunnel/cavern** with initial cost increase, but certainly pays off later during operations in case of problems!

CNGS – water issues





CNGS – water issues

29 CNGS water sumps - overview

Sump	Water source	Flow	Emptying	Volume	Comments
TCV4	<ul style="list-style-type: none">drain pipe work from upstream tunnels	0.5m ³ /d	20 days	180 m ³ /y	<ul style="list-style-type: none">can receive radioactive water in case of leaks in the ventilation system
TSG4	<ul style="list-style-type: none">target chamber drainscondensation water from ventilation system	3-20 lt/h	4-5/year	100 m ³ /y	<ul style="list-style-type: none">radioactive water (mainly H3) from the target areamanual emptying to containers
TNM41	<ul style="list-style-type: none">drains along the decay tube and hadron stop area	1-2 lt/h	4 fois/an	20 m ³ /y	<ul style="list-style-type: none">radioactive water along the decay tubehadron stop cooling system water in case of leakhigh PH value 12
Horns	<ul style="list-style-type: none">cooling system	Closed circuit (2x600lt)	~2-years	1.2 m ³ /2y	<ul style="list-style-type: none">radioactive water

- Dealing with the drain or infiltration water in underground areas is not trivial.
 - ▣ it took ~2 years to have infiltrations and thus (radioactive) water in the sump at the end of the decay tube
 - ▣ Sump at the end of the access tunnels is finally too close to the target area and its services
 - since this year we observe increased radioactivity levels in there without being able to identify the source
- Getting the water out of the sumps at the end of the target chamber and decay tube not a trivial exercise



- **Lesson #12** : the issue of the drain water (piping, sumps, service & maintenance) needs to be carefully studied for future facilities
 - ▣ may impact on civil engineering costs
 - ▣ separate and isolate as much as possible the radioactive areas and tunnels – if something goes wrong we may end up with large quantities of water to handle
 - ▣ transporting water tanks (or pipes) in steep slopes (i.e future installations !!) not an easy issue



Summary

31

- Making and operating high-intensity beam facilities is always an interesting challenge !!
- In CNGS lot of effort was put in the project/design phase to address most of the issues and learn from the available expertise and experience
- We are now collecting experience in operating the facility that is important to share with other colleagues
- The problems we faced were successfully resolved thanks to the competences and motivation of several colleagues from many CERN groups and external teams
- We hope our problems were really child diseases of the facility and we look forward to the interesting physics results from the Grand Sasso experiments - hopefully soon!