


MIT runs


TTL trigger from delay box
CH A to syn



No Label was not connected

SMD Camera Manual Description

DATA




SYNC

NO LABELED

RG39 Cable from TTL converter
to “NO LABEL”, NOT “SYNC”

**This Photo shows the previous connection when I did “Manual” Triggering.
NOT CURRENT CONFIGURATION**




**When I received it,
The BNC adaptor was connected to
“NO LABELED” SMA connector.
External Triggering did not work.**


**CONFIRMATION :
Currently the BNC adapter is
switched to “SYNC”
External Triggering did work.**

TTL trigger from delay box
CH A to “SYNC”, NOT “No Label”

Current Configuration in Tunnel




One BNC adaptor to "SYNC"



TTL Module is disconnected

<http://www.epixinc.com/products/ttlmod.htm>


Converts TTL Trigger to Differential for input into PIXCI Board
Converts PIXCI Board Differential Strobe Output to TTL



We don't need this TTL module.

So I disconnected the RS-39 cable.

Camera is triggering using BNC input through "SYNC" as we did at MIT.




Lens mount alignment : The gap between camera and objective lens was very small. The focusing adjuster roatated stiff. Camera holding bar and XY stage holding bar Were rotated.
NOT WELL MOUNTED NOW. IT WAS ASSEMBLED AT BNL. NEVER DISASSEMBLED AFTER IT LEFT BNL.

“pcmerit08” is installed.

- outlet : 3009/15
(3 outlet left in tunnel)**
- IP address : 137.138.184.21**
- connected to iboot4**

Current Scope Trace

Triggered Time



T (Master Triggering) = To
To from DG535


T (Master Triggering) = To
Synchronized Laser Pulse
Triggering Signal from
GaGe Board Output
17 pulse, 0.1 ms period
Delay from To was about
0.005 ms.

SMD Camera Triggering
Signal. A from DG535
A = To + 0.000000000 s


Photodiode signal
from scintillating fiber

TDS 2024B - 9:47:58 PM 9/13/2007

Viewport 1, Sep. 5, 2007



Viewport 1, Sep. 13, 2007




**Brightness changes suddenly.
Possibly optics problem.**


**The edge is very sharp.
Possibly optics may got damaged.**

**Circle is shifted. Alignment is broken.
Window is not clear.**

Viewport 2, Sep. 5, 2007





Viewport 2, Sep. 13, 2007



**Window is not clear.
Brightness changes suddenly.
No field of view is visible.**

Viewport 3, Sep. 5, 2007


Viewport 3, Sep. 13, 2007



**Focusing of left side was changed.
Alignment changed slightly.**

ALMOST SAME

Viewport 4, Sep. 5, 2007





1 ms fps

0.05 ms shutter


1 W laser used.
CW pulse for 0.5 s
12db+12db attenuator used
Able to use same control
input signal with FV camera.

Viewport 4, Sep. 13, 2007



0.1 ms fps



17 frames Read Out



**25 W laser used.
0.1 ms period laser pulse
17 pulses, total 1.7 ms light

Laser Intensity is LOW
17 frames Read Out**


Viewport 4, Sep. 13, 2007



**External Triggerring
Camera "Trigger IN"**

1.7 ms fps


1 frames Read Out



**25 W laser used.
0.1 ms period laser pulse
17 pulses, total 1.7 ms light**

**Field of View is visible clearly
OBJECTIVE LENS IS NOT WELL MOUNTED**

Viewport 4, Sep. 13, 2007



**External Triggerring
Camera "Trigger IN"**


0.5 ms fps

**4 frames Read Out
Frame does read out
correctly corresponding
to the laser time.**

**25 W laser used.
0.1 ms period laser pulse
17 pulses, total 1.7 ms light**

Viewport 4, Sep. 13, 2007

1W laser, 0.5s CW pulse, 0.5 ms fps




0.5 ms fps

17 frames Read Out

SWITCHED to 1 W Laser CW for 0.5 s

Moving Fan image



Manual triggering
0.1 ms fps.
17 frames.
8, 12(default), 16 bit file save support.
jpg, tif, ...etc support.
Possible to save files
Independently.
Possible to save files in
one file. But the file size
Increases up to 10 Mbyte
because it saves all of the buffer
Images (180EA).

No 14 degree rotation
Different with previous software

Software shows like this.
Not real

CONFIRMATION

- ALL COMPUTERS / EQUIPMENT ARE ABLE TO DO POWER RECYCLE AND CONTROL REMOTELY AND ALL 4 IBOOT IS WORKING
- SMD CAMERA IS WORKING CORRECTLY AND RESPOND CORRECTLY TO THE EXTERNAL TRIGGERING INPUT
- ALL 4 CAMERAS WORK SIMULTANEOUSLY

THINGS TO BE RESOLVED

- SHOULD OPEN THE SNOOT AGAIN AND INSPECT OPTICS STATUS AND THEN REPAIR/REALIGN OPTICS. BE PREPARED FOR THAT.
→ PREREQUISITE : THOMAS SHOULD COME AND COOPERATE WHEN THERE IS A CHANCE TO OPEN THE SNOOT.
WE HAVE ONE EXTRA OPTICS-FIBER SET. JUST IN CASE, WE CAN REPLACE ONE VIEWPORT.
- SHOULD MOUNT SMD OBJECTIVE LENS AGAIN. THE SPACE WAS VERY TIGHT AND NOT HOLDED TIGHTLY.
- CHECK 25W LASER INTENSITY. HOW? SOFTWARE DIFFERENCE? CONNECTION WAS ALREADY CHECKED AGAIN.
NOW USED MAXIMUM INPUT VOLTAGE, -20V