



MERIT Solenoid Update


- At the MIT system integration test a leak of LN₂ was observed when the cryostat was filled with LN₂ and 5bar pressure was applied to force a purge of the liquid.
- Some escaping gaseous N₂ was also observed
- Attempts were made at MIT to mitigate the problem before shipment to CERN but reception testing above ground demonstrated that the problem persisted.

Solenoid Electrical Feedthrough



Source of the problem located

Radial cracks
observed in
several
silicone
packing
disks





Compression
Fixture


Compression Test with GoreTex



The GoreTex after compression



Test Packing Scheme



The packing test fixture





The loading end

The “lead” end




With washers




Installing the GoreTex





Introducing LN2



Filled with LN₂
No leaks observed
With 1 bar ambient
pressure

10bar Water Test
No Leaks observed




Test with 10bar He

No Leaks observed at room temperature



10bar He at 77°K



Cryo Testing Results

- 2.5×10^{-5} mbar l /s Ambient Background
- No observed leak at 10bar Room Temp
- Initial cooldown, flush: substantial leak
- Further tighten by closing gap 1.3mm
- 1.3×10^{-3} mbar l /s leak rate
- Shock cooled in LN₂ bath
- 3rd cycle cooldown
- 0.8×10^{-3} mbar l /s leak rate → 12 mg/day

The Reassembly Work



May 29, 2007

Status as of 31 May

- We are now prepared to test the revised packing solution with a cryotest of the solenoid at 80⁰K.